

Faraz Oil Sulfur

Characteristics	Unit	Specification	Test Method
Purity (on dry basis)	% wt	Max 99.7	B.S.4113
Hydrocarbon	% wt	Max 0.09	B.S. 4113
Moisture Content	% wt	Min 0.8	B.S. 4113
Acidity (as H ₂ SO ₄)	% wt	Max 0.02	ISO 3704
Ash Content	% wt	Max 0.09	ISO 3425
Color	-	Bright Yellow	Visual